

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1






Fig. 2 A



Ridge Waveguide Bend and Probe Details.



Radiating Surface and Waveguide Body Decomposition






FIG. 2C



Ridge Waveguide Details 12






Fig. 4A








FIG 4B

Inverted L shape Waveguide Details





Inverted L shape Waveguide Body and Radiating Surface Details








Fig. 5 A



Inverted L Shape Bend and Probe Decomposition Details



Inverted L Shape Waveguide Bend and Probe Details




Fig. 7




Fig. 8

2-element beam forming - Center at Elv 65, Mod beam shift 90 deg in Combiner




Fig. 9A

2-element beam forming - Center at Elv 30, Mod beam shift 90 deg in Combiner




Fig. 9B




Fig. 10